

2019Z 31 DEC 63

TOP SECRET

TO : DIRECTOR

25X1A FROM :

ACTION: OPS (1-12)

INFO :

TOR 2120Z 31 DEC 63

PRIORITY

IN 56809

25X1A

25X1A TO PRIORITY INFO PRIORITY 25X1A

A. 6070

25X1A

B. 112A CAMERA/5808 FT C. PROCESSED ON TRENTON NBR. 2 AT MAX DEV. THRU-OUT. PRIMARY
74, SECONDARY 67.5 DEGREES.

D. GAMMA HEAD 2.47, TAIL 2.56

E. 4404 (SO-132) /43-11-11-3

F. QUALITY EVAL.

1. RECEIVED DRY ON 3 SPOOLS.

2. ADEQUATE

3. CONTRAST IN PERCENT - 70 LOW, 30 MEDIUM.

4. GOOD


5. GOOD - SEE PARA G

6. GOOD

7. N/A

G. THE FIRST 12 FRAMES OF THIS MISSION ARE HEAVILY FOGGED.
THIS FOGGING GRADUALLY DIMINISHES, FINALLY DISAPPEARING ON

TOP SECRET



REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy No.

T O P S E C R E T

25X1A

[REDACTED] (IN 56809)

PAGE TWO

FRAME 056. BANDING IS PRESENT 4 TO 5 INCHES INTO THE FORMAT AREA FROM THE PORT SIDE OF EACH FRAME. A SOFT FOCUS AREA IS NOTED ALONG THE STARBOARD, TRAILING EDGE OF THE FORMAT. THIS AREA IS LOCATED 1.5 TO 3.5 INCHES FROM THE STARBOARD EDGE AND APPROXIMATELY 0.5 INCHES INTO THE FORMAT AREA. A SERIES OF PARALLEL MINUS DENSITY STREAKS ARE NOTED ACROSS THE FORMAT AND ROUGHLY PARALLEL TO THE FILM EDGES THRU-OUT. FOUR SHORT SCRATCHES OCCUR 0.3, 1.9, 2.1, AND 3.1 INCHES FROM THE PORT EDGE OF EACH FORMAT AREA. THESE SCRATCHES ARE ALONG THE LEADING EDGE OF THE FILM AND OUTSIDE THE FORMAT AREA. THE TAKE, ARRIVING ON 3 SEPARATE SPOOLS CAUSED A SMALL PORTION OF FRAMES 786 AND 1481 TO BE DAMAGED DUE TO THE CUT AND SPLICE. THERE ARE 2191 TITLED FRAMES ON THIS MISSION. CLOUD COVER BETWEEN 5 AND 10 PERCENT.

25X1A

H. HELD AT [REDACTED] FOR REPRODUCTION PURPOSES.

-END OF MSG-

T O P S E C R E T